

---

# AN-520 Series Access Point Firmware

## Release Notes

---

### Firmware v1.4.00 Release Notes

<b>Release date</b>	2025-05-29
<b>Firmware version</b>	1.4.00
<b>Product SKUs affected</b>	AN-520-AP-I AN-520-AP-I-1

#### Fixes

- Resolved various cybersecurity issues.
- Fixed Web Sessions not timing out/expiring.
- Fixed the Site Survey to display SSIDs with commas.

#### Improvements

- Updated OvrC agent to improve internet outage reconnection reliability.
- Updated the API for DHCP lease time for the built-in guest network feature.
- Updated error messages for various fields throughout the local UI.
- Updated the System Name requirements to no longer allow a period (.) or hyphen (-) as the first or last character.
- Updated the connected client list to show clients connected to the built-in guest network.
- Updated MC/BC default value logic and threshold.

- Added support for OWE as a security mode for SSIDs.
- Improved logic around the display of an unknown hostname in the client list.

## Firmware v1.3.00 Release Notes

<b>Release date</b>	2024-11-07
<b>Firmware version</b>	1.3.00
<b>Product SKUs affected</b>	AN-520-AP-I AN-520-AP-I-1

### Fixes

- Fixes the OvrC Wi-Fi Management Site Survey Tool.

## Firmware v1.2.00 Release Notes

<b>Release date</b>	2024-04-25
<b>Firmware version</b>	1.2.00
<b>Product SKUs affected</b>	AN-520-AP-I AN-520-AP-I-1

### Improvements

- Updated the NTP server options.
- Updated form field validation for ACL blacklist/whitelist accepted characters.
- Added more advanced settings to support IoT heavy installations (DTIM + Directed MC/BC threshold).
- Added the ability to select radios for the primary SSID.

- Various security updates.
- International models: Updated the country code.

## Fixes

- Fixed a caching issue where a default UI screen would show up when refreshing the browser window.
- Fixed an issue where Site Surveys took longer to complete than expected when DFS was enabled.

## Firmware v1.0.12 Release Notes

<b>Release date</b>	2022-12-06
<b>Firmware version</b>	1.0.12
<b>Product SKUs affected</b>	AN-520-AP-I AN-520-AP-I-1

- This is the initial release